

SPECIAL |









Machining Capabilities

CNC TURNING SERVICES SPECIFIC	CATIONS	
Machines	CNC Lathes	
Runout	0.001 mm	
Max Part Dia.	400 mm	
Max Part Length	650 mm	
Machine Fixturing	Three-jaw chuck; Four-jaw chuck	
CNC MILLING SERVICES SPECIFICATIONS		
Machines	Machining Centers	
Runout	0.001 mm	
CNC Max Part Length	800 mm	
CNC Max Part Width	500 mm	
CNC Max Part Depth	500 mm	
GRINDING SERVICES SPECIFICATI	ONS	
Machines	Cylindrical, Internal and Surface Grinding Machines	
Cylindrical Grinding Machine Runout	0.001 mm	
Cylindrical Grinding Max Part Dia.	200 mm	
Cylindrical Grinding Max Part Length	1000 mm	
Internal Grinding Machine Runout	0.001 mm	
Internal Grinding Max Part Dia.	100 mm	
Internal Grinding Max Part Length	500 mm	
Internal Grinding Max Part Depth	150 mm	
Surface Grinding Machine Runout	0.005 mm	
Surface Grinding Max Part Length	400 mm	
Surface Grinding Max Part Width	250 mm	
Surface Grinding Max Part Height	400 mm	
SECONDARY SERVICES OFFERED		
Heat Treatment	Engineers are capable of designing heat treatment cycles for Annealing, Normalizing, Hardening, tempering, carburizing, etc.	
Surface Treatment	Blackening; Plating; Sandblasting, etc.	

BRIGHT



加工能力及范围

车削技术参数	
机器设备	数控车床
机床精度	0.001 mm
工件最大加工直径	400 mm
工件最大加工长度	650 mm
机床夹具配置	三爪;四爪
	₽.
机器设备	加工中心
机床精度	0.001 mm
工件最大加工直径	800 mm
工件最大加工宽度	500 mm
工件最大加工深度	500 mm
机器设备	外圆磨床;内孔磨床;平面磨床
外圆磨床精度	0.001 mm
外圆磨床工件最大加工直径	200 mm
外圆磨床工件最大加工长度	1000 mm
内圆磨床精度	0.001 mm
内圆磨床工件最大加工直径	100 mm
内圆磨床工件最大加工长度	500 mm
内圆磨床工件最大加工深度	150 mm
平面磨床精度	0.005 mm
平面磨床工件最大加工长度	400 mm
平面磨床工件最大加工宽度	250 mm
平面磨床工件最大加工高度	400 mm
其他服务	
th (N. TE	工程师有能力编排热处理相关工艺, 如退火、
热处理	正火、淬火、回火、调质、渗碳等。
	正人、什人、四人、炯灰、沙峽寺。
表面处理	发黑、电镀、喷砂等等





Main Manufacturing Procedure	主要加工步骤
 Drilling 	● 钻
Turning	● 车
Milling	● 铣
 Grinding 	● 磨
 Heat Treatment 	● 热处理
 Surface Treatment 	● 表面处理
 Assembling 	● 组装
Packing	● 包装

CNC Machining Service Procedures 机械加工下单流程

CNC Machining Service Procedures		
INQUIRY	Detailed information are required for quotation as company details, drawings, order quantity, delivery time, etc.	
QUOTATION	Calculate the cost and quote.	
ADVANCE PAYMENT	Make PI for payment after received purchaser order.	
MANUFACTURING	Redraw and assign manufacturing tasks; quality control during the whole process.	
FINAL Q.C.	Final quality inspection according to C=0 AQL=4%	
BALANCE PAYMENT	Balance Payment is required before shipment.	
PACKING & SHIPPING	Pack and ship according to customers' requirements.	
DOCUMENTS & LOGISTICS	Provide shipping documents after shipment.	